Inspection News & Views from the American Society of Home Inspectors, Inc.



VERMICULITE in the Attic p.10

վլիրերկիլիկենի արժկինայունների կեր

 SEPTILE WA 98146-2845

 444 SW 122ND ST
 4264


 HOME INSPECTIONS OF PUGET SOUND
 74

 JUGREIVE
 P. 2

 ACENTILE WA 98146-2845
 74

SERVICE DROP | 14

- Nice House, but is it Legal? | 18
- THE WORD: Electricity: Basic Theory | 20
 - ASHI Annual Reports for 2012 | 22
 - Just Thinking Out Loud | 38



By DAVID GRUDZINKSI, ACI


A WORSE-CASE SCENARIO — that's what I found in the attic of a home I recently inspected. Although this wasn't the first time I found evidence that some contractors have no clue about how to work around attic insulation, this time qualified as a worsecase scenario because the insulation was vermiculite.

ACCORDING TO the U.S. Environmental Protection Agency (EPA), there is no known safe level of exposure to asbestos and most of the vermiculite used for insulating purposes in the United States came from a mine near Libby, Montana, that was contaminated with tremolite asbestos. The product was sold under the name Zonolite. The EPA recommends treating all vermiculite insulation as if it is contaminated with asbestos. Asbestos fibers must be airborne to cause a health risk; therefore, when vermiculite insulation is disturbed, it should be assumed that tiny, lightweight asbestos fibers are being carried in the air.

The occupants of the home I was inspecting knew nothing about vermiculite insulation, including the risks created by disturbing it or having it enter their living space by paths created by a contractor.

Stirring up the fibers

From the attic hatch's pull-down stairs, I photographed the bath fan (see photo at right), which had been blowing the product around the attic for years. Knowing how poorly hatches with pull-down stairs seal, I identified this as one path for asbestos being released into the living space.











PHOTOS COURTESY OF DAVID GRUDZINSKI

To make matters worse, fabric and carpets had been tossed in the attic, as you can see in the four photos above. Vermiculite can be seen under and on top of the debris. It will have to be disturbed further to remove the fabric and debris.



Duct creates path

The air conditioning duct (on the right in the photo at left) was installed through the ceiling and down into a closet. No measures were taken to contain the vermiculite, and it has spilled into the living space another path for contamination.

In the photo at the right, you can see where vermiculite has fallen out of the ceiling because an AC duct was installed.





Vermiculite in the ducts

And, what may be the worst in this worsecase scenario, the air handler in the attic is sitting in and on vermiculite. I observed vermiculite inside the return duct, leading me to believe that asbestos probably is being blown through the air into the house every time the blower runs — yet another path.

Seller balks; buyer walks

I assume the homeowner and the contractor had been equally unaware of the health risks presented by vermiculite and of how it should be handled. Because my client still was interested in the property, I advised him to consult a professional remediation contractor. Nevertheless, even when informed, the owner did not want to address the issues, so my client moved on.

ASHI Certified Inspector David
Grudzinski started Advantage Home
Inspections in Cranston, Rhode Island,
after 20+ years in construction and
five years building luxury sailboats. He
is a former firefighter/EMT assistant
paramedic. Married to wife Regina and
father of four, his son Jamison has
joined the inspection company.

EPA Recommendations on Vermiculite

- Leave vermiculite insulation undisturbed in your attic or in your walls.
- Do not store boxes or other items in your attic if it contains vermiculite insulation.
- Do not allow children to play in an attic with vermiculite insulation.
- Do not attempt to remove the insulation yourself.
- Hire a professional asbestos contractor if you plan to remodel or conduct renovations that would disturb the vermiculite in your attic or walls to make sure the material is safely handled and/or removed.

For additional information, go to www.epa.gov/asbestos/vermiculite.html#exposure

Technical Review Committee Expresses an Opinion

The ASHI Technical Review Committee would like to point out that the ASHI Standards of Practice specifically excludes any requirement to inspect for or comment on asbestos and other environmental hazards. Many members, including some on the Technical Committee, object to the idea that ASHI should be featuring articles or social media commentary about a topic that's outside the scope of our standards because they feel that it contributes to an elevation in the standard of care that we will be held to in the event of a lawsuit.